# **MSDS** Material Safety Data Sheet Alpha Associates, Inc.



Alpha Maritex Style 3201-2-SS

#### MSDS Number: 0842

Revision Date: 6/22/2010

Page 1 of 4

1

#### PRODUCT AND COMPANY IDENTIFICATION

#### Manufacturer

Alpha Associates, Inc. 145 Lehigh Avenue

#### Lakewood, NJ 08701

**Contact:** James Palmer Telephone Number: 732-634-5700 FAX Number: 732-634-1430 E-Mail: jpalmer@alphainc.com Web www.alphainc.com

Product Name:	Alpha Maritex Style 3201-2-SS
Revision Date:	6/22/2010
MSDS Number:	0842
Common Name:	Silicone Coated Glass Fabric

2

3

#### **COMPOSITION/INFORMATION ON INGREDIENTS**

Fibrous Glass (CAS 14808-60-7) ACGIH TLV: 10 milligrams per cubic meter of air fiber diameters of less than 7 microns

Compounded silicone coating

#### **HAZARDS IDENTIFICATION**

**Route of Entry:** This material may enter the body through inhalation of nuisance dust. **Target Organs:** Respiratory system Inhalation: Sore, raspy throat Skin Contact: Redness and possible rash; itching Eye Contact: Itching and redness Ingestion: N/A

#### **FIRST AID MEASURES** 4

Inhalation:	Remove person to fresh air. If condition persists, seek medical attention.
Skin Contact:	Rinse with copious quantities of cool water. If rash or itching persists, seek medical attention.
Eye Contact:	Rinse with water. Do not rub eyes. Seek medical attention.
Ingestion:	Not applicable.

# **MSDS** Material Safety Data Sheet Alpha Associates, Inc.



Alpha Maritex Style 3201-2-SS

#### MSDS Number: 0842

5

6

8

9

Revision Date: 6/22/2010

Page 2 of 4

## FIRE FIGHTING MEASURES

Flash Point (Method Used): >250 C by TOC Flammable Limits

LEL: N/A UEL: N/A

Extinguishing Media: Water, carbon dioxide, or dry chemical

Special Fire Fighting Procedures: Thermal decomposition of fiber coating may produce an irritating mixture of smoke and fumes.

Unusual Fire and Explosion Hazards: None

# **ACCIDENTAL RELEASE MEASURES**

Material is a solid in roll form. If accidently released, rewind material back onto roll.

7	HANDLING AND STORAGE	
Handling Precaution Storage Requiremen		

### **EXPOSURE CONTROLS/PERSONAL PROTECTION**

**Engineering Controls:** Local exhaust; dust collection **Protective Equipment:** Safety glasses; cotton gloves; long sleeve clothing Exposure Guidelines/Other: Wash thoroughly with soap and water after handling

PHYSICAL AND CHEMICAL PROPERTIES

Appearance:	Silver Coated Fabric		
Physical State:	Solid	Boiling Point:	N/A
Odor:	No Odor	Freezing/Melting Pt.:	> 1000 F
pH:	N/A	Solubility:	Negligible
Vapor Pressure:	N/A	Spec Grav./Density:	2.4
Vapor Density:	N/A		

# **MSDS** Material Safety Data Sheet Alpha Associates, Inc.

# Alpha Maritex Style 3201-2-SS



MSDS Number: 0842

Revision Date: 6/22/2010

Page 3 of 4

10	STABILITY AND REACTIVITY	
Stability:		Material is stable.
Conditions to avoid:		None known.
Materials to avoid (ir	ncompatability):	Strong oxidizing agents.
Hazardous Decompo	sition products:	Carbon monoxide; carbon dioxide
Hazardous Polymeri	zation:	Will Not Occur.

11

# **TOXICOLOGICAL INFORMATION**

Direct contact with fiberglass materials or exposure to airborne fiberglass dust may irritate the skin, eyes, nose and throat. Fiberglass can cause itching due to mechanical irritation from the fibers. This is not an allergic reaction to the material. Breathing fibers may irritate the airways resulting in coughing and a scratchy throat. Some people are sensitive to the fibers, while others are not.

12

## **ECOLOGICAL INFORMATION**

No known hazards except for airborne fibers caused by nuisance dust. 10 milligrams per cubic meter for fiber diameters less than 7 microbes.

13

15

## **DISPOSAL CONSIDERATIONS**

Burial in a federal, state, or local approved landfill.

14 **TRANSPORT INFORMATION** 

None special required.

# **REGULATORY INFORMATION**

COMPONENT / (CAS/PERC) / CODES

\*Silica, crystalline (14808607 n/a%) MASS, NRC, OSHAWAC, PA, TXAIR

REGULATORY KEY DESCRIPTIONS

MASS = MA Massachusetts Hazardous Substances List NRC = Nationally Recognized Carcinogens OSHAWAC = OSHA workplace Air Contaminants PA = PA Right-To-Know List of Hazardous Substances TXAIR = TX Air Contaminants with Health Effects Screening Level

16



Alpha Maritex Style 3201-2-SS



MSDS Number: 0842

Revision Date: 6/22/2010

Page 4 of 4

END OF MSDS DOCUMENT